



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 2-26-2021
 Facility name: East Palestine Waste Water
 Ohio NPDES permit no.: 3PD00042*LD
 Period covered by report: 2020


Contact person

Name: John Jurjavic
 Title: Superintendent
 Mailing address: P.O. Box 231 East Palestine, Ohio 44413
 Telephone: (330)426 - 7062
 Email: johnwwtp@sbcglobal.net

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name John Jurjavic Title: Superintendent
 (typed):

Signature: 

Date: 26 Feb. 2021

SSO Annual Report Table 1: SSO Identification

Ohio NPDES Permit No.:

Identification No. ^A	Location Description	Receiving Water ^B	Eliminated ^C
301	Park DR. Siphon 20 Park Dr.	Leslie Run	N/A
302	MH#5 SS#4 W. Main St./Vine St.	Leslie Run	0.06mgd

- A. Assign each SSO location a unique identification by numbering them consecutively, beginning with 301.
- B. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter (None".
- C. If an SSO has been eliminated, enter the date of elimination (MM/DD/YY).

Enter narrative analysis of WIB patterns by location, frequency and cause.

Locations 301 and 302 are the spots that back up during heavy rain. We try to alleviate the system by pumping at MH#5 SS#4 To take the hydraulic load from the plant and prevent the flooding of basements. The Siphon alleviates its self due to the construction of this structure. The Village is in construction of building a 1.2million gallon tank for strom water retention. Hopefully this will alleviate the backups in the syste during heavy rains.